



PRINTABLE

Crush

EASYPRESS GUIDE

INCLUDES THE
MOST COMMON
BASE MATERIALS AND
CRICUT IRON-ON
PRODUCTS

EASYPRESS GUIDE

BASE MATERIAL	EVERYDAY IRON-ON	FOIL IRON-ON	GLITTER IRON-ON	HOLOGRAPHIC IRON-ON	SPORFLEX IRON-ON™	PATTERNED IRON-ON™	IRON-ON DESIGNS™	FUSIBLE FABRIC
100% COTTON	315°F / 155°C 30 SECONDS WARM GENTLE	295°F / 145°C 30 SECONDS COLD GENTLE	330°F / 165°C 30 SECONDS WARM GENTLE	330°F / 165°C 30 SECONDS WARM GENTLE	NOT RECOMMENDED	340°F / 170°C 50 SECONDS COLD FIRM	340°F / 170°C 50 SECONDS COLD FIRM	315°F / 155°C 30 SECONDS
COTTON/POLY BLEND	315°F / 155°C 30 SECONDS WARM GENTLE	295°F / 145°C 30 SECONDS COLD GENTLE	330°F / 165°C 30 SECONDS WARM GENTLE	330°F / 165°C 30 SECONDS WARM GENTLE	NOT RECOMMENDED	340°F / 170°C 50 SECONDS COLD FIRM	340°F / 170°C 50 SECONDS COLD FIRM	315°F / 155°C 30 SECONDS
POLYESTER	315°F / 155°C 30 SECONDS WARM GENTLE	295°F / 145°C 30 SECONDS COLD GENTLE	330°F / 165°C 30 SECONDS WARM GENTLE	330°F / 165°C 30 SECONDS WARM GENTLE	305°F / 165°C 30 SECONDS WARM GENTLE	NOT RECOMMENDED	NOT RECOMMENDED	315°F / 155°C 30 SECONDS
NYLON	280°F / 140°C 30 SECONDS WARM GENTLE	255°F / 125°C 30 SECONDS COLD GENTLE	NOT RECOMMENDED	NOT RECOMMENDED	305°F / 165°C 30 SECONDS WARM GENTLE	NOT RECOMMENDED	NOT RECOMMENDED	NOT RECOMMENDED
SILK	280°F / 140°C 30 SECONDS WARM GENTLE	255°F / 125°C 30 SECONDS COLD GENTLE	NOT RECOMMENDED	NOT RECOMMENDED	NOT RECOMMENDED	NOT RECOMMENDED	NOT RECOMMENDED	305°F / 150°C 30 SECONDS
MESH	280°F / 140°C 30 SECONDS WARM GENTLE	280°F / 140°C 30 SECONDS COLD GENTLE	NOT RECOMMENDED	NOT RECOMMENDED	NOT RECOMMENDED	NOT RECOMMENDED	NOT RECOMMENDED	315°F / 155°C 30 SECONDS
COTTON CANVAS	340°F / 170°C 30 SECONDS WARM GENTLE	290°F / 145°C 30 SECONDS COLD GENTLE	270°F / 130°C 30 SECONDS WARM GENTLE	285°F / 140°C 30 SECONDS WARM GENTLE	NOT RECOMMENDED	340°F / 170°C 50 SECONDS COLD FIRM	340°F / 170°C 50 SECONDS COLD FIRM	330°F / 165°C 30 SECONDS
FELT	280°F / 140°C 30 SECONDS WARM GENTLE	280°F / 140°C 30 SECONDS COLD GENTLE	270°F / 130°C 30 SECONDS WARM GENTLE	285°F / 140°C 30 SECONDS WARM GENTLE	NOT RECOMMENDED	265°F / 130°C 20 SECONDS COLD FIRM	265°F / 130°C 20 SECONDS COLD FIRM	305°F / 150°C 30 SECONDS
FAUX LEATHER	280°F / 140°C 30 SECONDS WARM GENTLE	255°F / 125°C 30 SECONDS COLD GENTLE	270°F / 130°C 30 SECONDS WARM GENTLE	285°F / 140°C 30 SECONDS WARM GENTLE	NOT RECOMMENDED	265°F / 130°C 20 SECONDS COLD FIRM	265°F / 130°C 20 SECONDS COLD FIRM	NOT RECOMMENDED
CARDSTOCK	280°F / 140°C 30 SECONDS	270°F / 130°C 30 SECONDS	290°F / 145°C 30 SECONDS	290°F / 145°C 30 SECONDS	NOT RECOMMENDED	290°F / 145°C 30 SECONDS	290°F / 145°C 30 SECONDS	NOT RECOMMENDED
CORKBOARD	315°F / 155°C 15 SECONDS	NOT RECOMMENDED	315°F / 155°C 15 SECONDS	315°F / 155°C 15 SECONDS	315°F / 155°C 15 SECONDS	315°F / 155°C 15 SECONDS	315°F / 155°C 15 SECONDS	NOT RECOMMENDED
CHIPBOARD	315°F / 155°C 30 SECONDS	NOT RECOMMENDED	315°F / 155°C 30 SECONDS	315°F / 155°C 30 SECONDS	NOT RECOMMENDED	315°F / 155°C 30 SECONDS	315°F / 155°C 30 SECONDS	NOT RECOMMENDED

Want More?

If you have any questions, you can probably find the answer in my [Cricut Machine Tutorials](#).

In case you need CDS Space help, here are my most popular tutorials:

- [How to Edit Text in Cricut Design Space](#)
- [How to Create Custom Designs in Cricut Design Space](#)
- [11 Reasons You Need a Cricut Access Subscription](#)
- [How to Customize a Cricut Access Project](#)
- [How to Upload Patterns to Cricut Design Space](#)
- [How to Upload Print and Cut Files to Cricut Design Space](#)
- [How to Upload SVG Files to Cricut Design Space](#)
- [How to Create a Cricut Print and Cut Project from SVG Files](#)
- [How to Use the Slice Tool to Make Large Vinyl Decals](#)
- [How to Use the Weld Tool in Cricut Design Space](#)
- [How to Use the Cricut Contour Tool with SVG Files](#)
- [How to Design Custom Invitations in Cricut Design Space](#)
- [Make Your Own Invitations from SVG Files in Cricut Design Space](#)
- [How to Make Gift Tags from SVG Files in CDS](#)



BE SURE TO CHECK OUT THE *latest* CRICUT TUTORIALS

